

**TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer /Assistant Executive Engineer)**

1 Name of School : MARY MATHA ENGLISH SCHOOL
 2 Name of officer : Anitha C T
 3 Location : Cheruthazham
 4 Period for which the certificate issued : 01-06-2023 to 31-05-2024
 5 Type of building :

R.C.C BUILDING

GF

1)Class room	2x6.35x6.35x3.7
2)Class room	2x6.35x6.15x3.7
3)Class room	2x6.35x6.20x3.7
4)Class room	1x6.35x6.00x3.7
5)Class room	1x6.14x6.25x3.7
6)Class room	1x6.02x6.25x3.7
7)Principal room	1x3.00x3.15x3.7
8) Manager room	1x3.00x3.00x3.7
9)Office room	1x9.35x6.20x3.7
10)Computer Lab	1x6.10x6.25x3.7
11)Class room	1x6.10x6.25x3.7
12)Library	1x6.24x6.25x3.7
13)Class room	1x6.24x6.05x3.7
14)Class room	1x6.24x6.01x3.7

FF

1)Class room	2x6.35x6.35x3.7
2)Class room	2x6.35x6.15x3.7
3)Class room	2x6.35x6.20x3.7
4)Class room	1x6.35x6.00x3.7
5)Class room	1x8.18x6.25x3.7
6)Class room	2x6.16x6.25x3.7
7)Class room	1x6.17x6.25x3.7
8)Computer Lab	1x4.90x6.20x3.7
9)Computer Lab	1x6.10x6.25x3.7
10)Class room	1x6.07x6.25x3.7
11)Library	1x7.98x6.25x3.7
12)Class room	1x8.25x6.25x3.7
13)Class room	1x6.24x6.05x3.7
14)Class room	1x6.24x6.01x3.7

SF

RCC Structure

1)Class room	1x6.34x6.25x3.7
2)Physics Lab	1x8.18x6.25x3.7
3)Chemistry Lab	1x9.35x6.25x3.7
4)Biology Lab	1x9.41x6.25x3.7
5)Music	1x4.37x6.25x3.7

Alu. Zinc Sheet

1)Class room	1x6.22x6.25x3.7
2)Class room	1x6.11x6.25x3.7
3)Class room	1x6.35x6.30x3.7

	4)Class room	1x6.35x6.08x3.7
	5)Class room	1x6.35x6.12x3.7
6	Nature of defects, if any	:
	a) Foundation and basement	:
	b)Super structure	:
	c)Door and Windows	:
	d)Wood work wrought and put up	: NIL
	e) Roof	:
	f)Flooring	:
	g)Misceliencous	:
7	Any major defects noticed which will render thebuilding unsafe in any manner	: No
8	Whether maintenance works have been done properly	: Yes
9	Whether the structure is sound or not for conducting classes	: Yes, the structure is safe for conducting classes under normal weather and wind conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind,exposure of flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 09 /06/2023 and found to be fit to conduct classes, for the period for the reasons stated above.

Place: Cheruthazham
Date: 09.06.2023

Signature:
Designation:

(Signature)
Assistant Engineer
LD & EW Section
Cheruthazham Grama Panehayat
P.O. Mendur - 670 501



(Signature)
MANAGER
Mary Matha English School
P.O. Pilathara - 670 504
Kannur Dt. Ph: 0497 2802010
No. CBSE/Aff.1930657