TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer / Assistant Executive Engineer)

1	Name of School	:	MARY MATHA ENGLISH SCHOOL
2	Name of officer		Anitha C.T.

Name of officer : Anitha C T
Location : Cheruthazham

4 the certificate : 01-06-2025 to 31-05-2026

5 Type of building :

R.C.C BUILDING

1)Class room	2x6.35x6.35x3.7
2)Class room	2x6.35x6.15x3.7
3)Class room	2x6.35x6.20x3.7
4)Class room	1x6.35x6.00x3.7
5)Class room	1x6.14x6.25x3.7
6)Class room	1x6.02x6.25x3.7
7)Principal room	1x3.00x3.15x3.7
8) Manager room	1x3.00x3.00x3.7
9)Office room	1x9.35x6.20x3.7
10)Computer Lab	1x6.10x6.25x3.7
11)Class room	1x6.10x6.25x3.7
12)Library	1x6.24x6.25x3.7
13)Class room	1x6.24x6.05x3.7
14)Class room	1x6.24x6.01x3.7
AND	

1)Class room	2x6.35x6.35x3.7
2)Class room	2x6.35x6.15x3.7
3)Class room	2x6.35x6.20x3.7
4)Class room	1x6.35x6.00x3.7
5)Class room	1x8.18x6.25x3.7
6)Class room	2x6.16x6.25x3.7
7)Class room	1x6.17x6.25x3.7
8)Computer Lab	1x4.90x6.20x3.7
9)Computer Lab	1x6.10x6.25x3.7
10)Class room	1x6.07x6.25x3.7
11)Library	1x7.98x6.25x3.7
12)Class room	1x8.25x6.25x3.7
13)Class room	1x6.24x6.05x3.7
14)Class room	1x6.24x6.01x3.7

SF

RCC Structure

1)Class room	1x6.34x6.25x3.7
2)Physics Lab	1x8.18x6.25x3.7
3)Chemistry Lab	1x9.35x6.25x3.7
4)Biology Lab	1x9.41x6.25x3.7
5)Music	1x4.37x6.25x3.7

6 Nature of defects, if

a) Foundation and t :

b)Super stucture

c)Door and Window : NIL

d)Wood work wrou

e) Roof f)Flooring

g)Miscelieneous

7 Any major defects : No 8 Whether : Yes

9 Whether the : Yes, the structure is safe for

Grama

Note: 1. The stability of the structure should be examined also with reference to

2. Any additional observations if deemed necessary for the certificate may be

CERTIFICATE

Certified that the school building was inspected by me on 24/05/2025 and found to be fit to conduct classes, for the period for the reasons stated above.

Place: Cheruthazham Date: 24.05.2025

Signature: Designation:

Cherutiazham Grama Panchayat
PO Mandur - 670 501